

TRIANGLE FASTENER CORPORATION

4661 Hinckley Industrial Parkway | Cleveland, OH 44109 Phone: (216) 351-9933 | Fax: (216) 351-5008

Website: www.trianglefastener.com

TECH CENTER

ROHS COMPLIANT CERTIFICATION

REPORT NUMBER: CC062018

Product: PIPE-MASTER® Pipe Flashing and BOND-SEAL™ Bonded Washers

Triangle Fastener Corporation certifies that these products are compliant with Directive ROHS 2 2011/65/EU known as the new ROHS Directive for Hazardous Substances as published in the official Journal of the European Union on January 7, 2011





"ROHS Compliant" means that the product or part does not contain any of the following restricted substances in excess of the following maximum concentration values tolerated by weight in homogeneous materials, unless the substance is an application that is exempt under ROHS:

Bis (2-ethylhexyl) phthalate (DEHP)
Butyl benzyl phthalate (BBP)
Cadmium (0.01%)
Dibutyl phthalate (DBP)
Diisobutyl phthalate (DIBP)
Directive 2011/65/EU: Article 4 (1), ANNEX II
Hexavalent chromium (0.1%)
Lead (0.1%)
Mercury (0.1%)
Polybrominated biphenyls (PBB) (0.1%)
Polybrominated biphenyl ethers (PBDE) (0.1%)

VICE PRESIDENT

Unless otherwise stated by Triangle Fastener Corporation in writing, this information represents Triangle Fastener Corporation's knowledge and belief based on information provided by suppliers to Triangle Fastener Corporation.

Certification beyond that described above will generally not be available. Please note that specific formula, composition or content information is proprietary and is therefore not available.

Rev. A 06-19-18 JK

DISCLAIMER: RESULTS ARE ULTIMATE VALUES ACHIEVED IN A LABORATORY ENVIRONMENT. ACTUAL JOBSITE CONDITIONS VARY AND CAN EFFECT RESULTS. APPROPRIATE FACTORS OF SAFETY SHOULD BE USED BY THE USER OR SPECIFIER. DETERMINING THE PROPER FASTENER IS THE RESPONSIBILITY OF THE USER OR SPECIFIER. BECAUSE APPLICATION CONDITIONS VARY AND ARE UNCONTROLLABLE BY TFC, WE ASSUME NO LIABILITY FOR THE USE OF THIS INFORMATION.